

**GOVERNMENT OF PUERTO RICO
PUERTO RICO PUBLIC SERVICE REGULATORY BOARD
PUERTO RICO ENERGY BUREAU**

NEPR Received: Apr 14, 2022 5:01 PM
--

IN RE: INTERRUPCIÓN DE SERVICIO
ELÉCTRICO DE 6 DE ABRIL DE 2022

CASE NO. NEPR-IN-2022-0002

SUBJECT:

**Submission in Compliance with Request
for Information on April 6th Incident**

**MOTION TO SUPPLEMENT PRELIMINARY REPORT ON APRIL 6TH INCIDENT
TO THE HONORABLE PUERTO RICO ENERGY BUREAU:**

COME now **LUMA Energy, LLC** (“ManagementCo”), and **LUMA Energy ServCo, LLC** (“ServCo”), (jointly referred to as the “Operator” or “LUMA”), and respectfully state and request the following:

1. On April 6th 2022, a failure in the electric system led to a fire at the Costa Sur transmission substation, which resulted in a power outage of the entire electrical system (hereinafter, the “April 6th Incident”).

2. On April 8th 2022, this Honorable Puerto Rico Energy Bureau (“Energy Bureau”) issued a Resolution and Order whereby it initiated a confidential investigation of the April 6th Incident (“April 8th Order”).

3. The April 8th Order instructs LUMA to submit on or before April 12th, 2022, at noon, a preliminary report on the causes of the April 6th Incident and the corrective actions taken by LUMA (the “Preliminary Report”), and requires submission of any information, in digital or tangible format regarding the incident in possession of LUMA and/or PREPA, which includes, but

is not limited to, data, graphs, maps, videos, audios, photos, reports, or documents related to the Incident and its effect on the electric service, the generation fleet, and the electricity transmission and distribution system of Puerto Rico.

4. On April 12, 2022, LUMA, in compliance with the April 8th Order, and to be transparent with its customers and regulators about its operations, LUMA submitted the Preliminary Report of the April 6th Incident. The Preliminary Report included the information that LUMA has gathered thus far and preliminary findings and assessments of the April 6th Incident.

5. The Preliminary Report included the following:
- i. Summary Information on the April 6th Incident;
 - ii. Incident chronology;
 - iii. Investigation;
 - iv. Damaged Equipment; and
 - v. Summary of Completed Actions and Next Steps.

6. In an effort to aid the Energy Bureau in its investigation and supplement the Preliminary Report, LUMA is submitting with this Motion, two (2) videos, including a screen recording from the Costa Sur transmission substation that shows a few minutes before and after the failure of oil circuit breaker number 0082 at the Costa Sur Substation's 230 kV switchyard on April 6th. The second is an aerial view video of the Costa Sur Substation taken the morning after the April 6th Incident. The videos will be submitted through electronic communication to the Energy Bureau, given the technical impossibility of uploading them to the electronic docket.

WHEREFORE, LUMA respectfully requests that the Energy Bureau **take notice** of the aforementioned and **accept** the videos submitted concurrently with this Motion as a supplement to the Preliminary Report of the April 6th Incident.

RESPECTFULLY SUBMITTED.

We hereby certify that we filed this Motion using the electronic filing system of this Energy Bureau and that we will send an electronic copy of this Motion to attorneys for PREPA, Katuska Bolaños-Lugo, kbolanos@diazvaz.law, and Joannely Marrero-Cruz, jmarrero@diazvaz.law.

In San Juan, Puerto Rico, this 14th day of April 2022.



DLA Piper (Puerto Rico) LLC
500 Calle de la Tanca, Suite 401
San Juan, PR 00901-1969
Tel. 787-945-9107/ 9132
Fax 939-697-6147/ 6102

/s/ Yahaira De la Rosa Algarín
Yahaira De la Rosa Algarín
RUA NÚM. 18,061
yahaira.delarosa@us.dlapiper.com

/s/ Iván Garau-González
Iván Garau-González
RUA NÚM. 20,229
ivan.garau@us.dlapiper.com

Exhibit 1

(to be submitted via email)